



American Gilsonite Company

Bonanza, UT 84008 • Phone (801) 789-1921

FAX (801) 780-1956

Bonanza Mining Operations

January 28, 1992

Mr. D. Wayne Hedberg, Permit Supervisor
UTAH DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203

Re: Annual Report for the Year 1991

Dear Mr. Hedberg:

Enclosed is the Annual Report of 1991 for Mine No. M/047/010. This is the Bonanza Mine of American Gilsonite Company with operating offices in Bonanza, Utah.

Should you have any questions please contact me at 789-1921, extension 60.

Sincerely,

Terry Tilley
Terry Tilley
Plant Superintendent

RECEIVED

JAN 31 1992

DIVISION OF
OIL GAS & MINING

RECEIVED

JAN 31 1992

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
Telephone: (801) 538-5340
Fax: (801) 359-3940

DIVISION OF
OIL GAS & MINING

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. GENERAL INFORMATION

1. Report Time Period: From (mo./yr.) 01/1991 To (mo./yr.) 01/1992
2. DOGM File Number: M/047/010
3. Mine Name: American Gilsonite Co. - Bonanza Operations
4. Mineral(s) Mined: Gilsonite
5. Legal Description (Location of Lands Affected): Uintah County
____1/4, ____1/4, Section _____, Township _____, Range _____
____1/4, ____1/4, Section _____, Township _____, Range _____
____1/4, ____1/4, Section _____, Township _____, Range _____
6. Name of Operator or Company: American Gilsonite Co.
7. Permanent Address: 136 E. South Temple, Suite 1460
Salt Lake City, Utah 84111-1104

8. Company Representative (or designated operator):

Name: Terry M. Tilley
Title: Plant Superintendent
Address: Bonanza Mine Site, Bonanza, Utah 84008
Phone: (801) 789-1921

☒ Please check if any of the above information has changed since previous year.

II. MINING AND RECLAMATION

1. Was the mine active during the past year? Yes ☒ No ☐

2. If active, how much ore or mineral was mined? 30,037

3. How much new or additional acreage was affected during past year? 1.5 acres

4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.

Approximately 2000 feet of new road was constructed in 1991.

5. How much acreage was reclaimed during past year? Approximately 5 acres.

6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.

Previously prepared 5 acres of ground was seeded in 1991.

7. What is the total disturbed acreage at years end? Approximately 48 acres.

8. Briefly summarize mining and reclamation planned for the upcoming year.

Plans are to develop one new mine site which will require about one acre of site clearing. There are no newly abandoned mine sites ready for reclamation, but some older sites may be reseeded during the year.

NOTE: Section III., "Additional Information" applies only to large mining operations.

III. ADDITIONAL INFORMATION

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. SIGNATURE REQUIREMENT

I hereby certify that the foregoing is true and correct.

Name (Typed or Print): Neldon H. Kunz

Title of Operator: Mine Superintendent

Signature of Operator: 

Date: 1/28/92

jb
MR-AR